

Port Glasgow.

10th Aug^r 1866

Messrs H. S. P. Bodd & Robt Lusk
Lloyd Surveyors

Gentlemen

The makers of the
Chains & Anchors for our
new Steamer "Iracian"
not being aware (apparently)
of the rigid application of
the minimum weight in the
case of Anchors - have sent
us an Anchor 46th to light
of which we enclose Certificate
along with those for other
Anchors & Cables -

We regret this, very much
as the vessel must sail on
the 15th inst & we should like
to have Certificate completed

The makers have not another
Anchor of the proper weight
to give us & cannot make
one in time nor get one
If your Committee will
be good enough to grant
Certificate at present - we
hereby engage to put one
board on the vessel before
here in about two months
an Anchor of the proper
weight & test

We are Gentlemen

Yours respectfully

W. D. McLean & Co



© 2021

Lloyd's Register
Foundation

IRON 500 - 0044