

Lloyd's Surveyors Office,
Hull 29th Decr 1866

Sir

In reply to your letter of the 28th
inst. requesting particulars as to the stores
of the S^{te} M^{re} "Don Antonia" Report No 3716
I beg to refer to the original Report where
the anchors are as follows. ^{est. 94 lbs} 28. 3. 21 ^{est. 94 lbs} 28. 2. 10 ^{est. 94 lbs} 28. 1. 10
being upwards of 4. on each Bower anchor in
accordance of the requirements of the Rules -

The vessel having previously been classed
12th 1 I did not require the anchors
to be re-tested, should the testing be required
I will apprise the owners so that they
may have the same carried out the first
opportunity, the vessel having now sailed

In re-classing of vessels at this Port if the
chains and anchors have to be tested there
will be many objections as there is no Public
Testing Machine nearer than Sunderland

I am, Sir, Yours truly,
Gt B Suffany Esq London
John W. Davidson
Lloyd's Register