



Revised length due to the softening and swelling
of some of upper back. This is a plastic
but the fossils beneath the clouds are not
to be seen. ^{See above} *Foram. sinensis*, and *Lept. Diet.*
Lept. alternata, on other frames
all better clouds visible

When plates should be fitted and riveted at ends
of stringer plate on alternate frames where all
hold beams or bulkheads.
Outside plating not to be reduced in height
at ends of vessel below the height within
by the rules



No 124 -
Jan'y 8th 1869

London
Jan^y 10/69



CHAS & WILL^M EARLE
ENGINEERS & IRON SHIPBUILDERS
HULL

© 2021
Lloyd's Register
Foundation

1R0501-0225 $3\frac{1}{3}$