

Lloyds' Register of Shipping,

West Hartlepool, 1st July 184th

The Secretary.

Sir, I beg respectfully to return the
First Entry Report on the S.S. "Black Watch"
with correction made on Main Deck Stringer. It
will be seen by the thickness of the tie plate
that it was a clerical error. With reference to the
plating of the Vessel the thick plating was in
Midships and the thin plating at the ends. Please
see approved Midship Section sent with Report
on the Vessel.

I am, Sir,

Your obedient Servant,

Wm. Minwell



© 2021

Lloyd's Register
Foundation

IRON 509-0041 1/2

For the Chief Surveyor to certify to
R.
2/1/74

0041 2/2



© 2021

Lloyd's Register
Foundation

For the Chief, Curwaga, Worcester
MA

1874

W. Standpool,
1st July
M. Bonniwell,

Recd. 2.

Ans.?

Black Watch



© 2021

Lloyd's Register
Foundation