

Lloyd's Register of Shipping
London 26th May 1875.

Gentlemen,

In accordance with your request we have made a careful examination of the Rudder and its fittings of your Iron S. S. "Glover" ²⁴⁸601 tons, as far as practicable, with the vessel afloat and having heard the circumstances of the case as detailed by Captain Ellis who asserts from hearsay evidence that the rudder is now twisted, also the evidence of Mr. Hawn the owners Superintendent, and Mr. Green the Society's Surveyor, who had carefully examined the vessel's Rudder in dry dock, and caused the twisting complained of to be remedied we are of opinion that the said rudder is thoroughly efficient.

We are, Gentlemen,

Your obedient Servants,
(Sgd) J. Williamson
Christ Besant
James Sibum.

Messrs Mounsey and Foster
Iron Shipbuilders,
South Docks.
Sunderland.



© 2021

Lloyd's Register
Foundation

IRON511-0269