

Lloyd's Register of British & Foreign Shipping.

Sunderland. 2<sup>nd</sup> to 4<sup>th</sup> October 1846.

~~Copy~~

This is to Certify  
that the undersigned Surveyors to this Society,  
did, at the request of James Sainq Esq., Survey the  
Iron Screw Steamer "Medusa"  $\frac{719}{1110}$  tons register, of  
Sunderland, while lying in the Cornhill Dry  
Dock here, for the purpose of ascertaining the  
extent of the damage she sustained from having  
stranded off Ashant on the morning of the 19<sup>th</sup> of  
September last, she being at the time laden with  
a cargo of fruit and bound from Cephalaria  
to London. For particulars see the Log Book  
and protest.

On examination found the edges of  
two adjoining plates on the starboard bilge slightly  
bulged inwards, that nine plates in various parts  
of the port flat had been badly bulged inwards,  
that on removing the said damaged plates  
four main frames were found to have been  
cracked and a few others bent; that the  
cement around the damaged shell plates  
had been started and cracked and otherwise



damaged.

The undersigned recommended that the nine damaged plates be removed on the port side; that all the other foregoing enumerated damages be made good or repaired as may be found necessary, that the bottom be cleaned and coated with paint, and that the vessel be put in all respects in as good and efficient condition as she was before the accident occurred.

(Sgd) J. Williamson  
Joseph Keen

Surrey fcu/52-2-0



© 2021

Lloyd's Register  
Foundation