

2696

Size of Bolts in Fastenings.

Surveyor's Name

Her Masts, Yards, &c. are in good condition, and sufficient in size and length.

She has SAILS.			CABLES, &c.		ANCHORS.	
N ^o .		Fathoms.		Inches.	N ^o .	
2	Fore Sails,	27	Chain	1 1/2	3	Bower,
2	Fore Top Sails,	100	Hempen Stream Cable.....		1	Stream,
2	Fore Topmast Stay Sails,	90	Hawser	9	1	Kedge,
2	Main Sails,	90	Towlines	7		All of proper weight.
2	Main Top Sails,	75	Warp	6		
and <u>two good weather sails</u>			All of <u>good</u> quality.			

Her Standing and Running Rigging is all sufficient in size and good in quality.

She has a Long Boat and Pinnace for 8 or 10 persons

The present state of the Windlass is good Capstan good and Rudder good
2 Pumps.

General Remarks—Statement and Date of Repairs.

7 Pair of diagonal standards under Deck.
Underhold beams. one pair of diagonal 1 IR connecting Bread Hook.
A pair of diagonal 1 IR with ladders attached with 2 bolts through floor
one pair of diagonal 1 IR after body 13 feet to side arms.
one pair of diagonal 1 IR 12 feet side arms.
Iron pair of footlock ladders from 16 feet to 15 feet long with 3 bolts in a
substantial part of the floor. The pillars under deck & hold beams
are connected with keelson lower hold & Deck beams with iron plates
all iron bolts in knives through strengthened — the commodore will observe
that there is 10 pair of plates in fastened — It was the owners order to his

Captain that the should be well fastened under hold beams. It was their
intention to have put in 4 more footlock ladders up to the last day the
shipwright promised to have them all ready, but disappointed them
In my opinion they have complied with the order the other 4 ladders
will be put in on her return

In an efficient state of repair at last day
Prescribed with safety

If Sheathed, Doubled, or Felted, single bottom
and Date when last done _____

And Sam of opinion this Vessel should be Classed A 1

The Amount of the Fee.....£ 5 : 5 : 0 is received by me, M. R. Hammett

Committee Minute 26 Feb 1839

Character assigned A 1 for 4 years

C. G.

W. B.



© 2009

Lloyd's Register
Foundation

26 Feb 1839
174