

3191
In the Survey of the Mary - you have entered
into many particulars of the repair done
to her since the year 1832 - She does
not appear to have been previously clapped
Have the repairs set forth as being done since
1834 been under your inspection, & if so, why
has she not been reported.

In the recent Survey, it would seem
that the rule section 63. has not been
fulfilled, & for this reason have deferred
the Clapping until the receipt of your
~~explanatory~~ reply, stating your reasons
for recommending her to the A. Clap



© 2019

Lloyd's Register
Foundation

LIV 575-0290