

# REPORT of SURVEY for REPAIRS.

No. *190* Survey held at *London* Date *November 2* 1835  
 on the *Ship Hashemy* Master *Hyde*  
 Tonnage *523* Built at *Calcutta* When built *1817*  
 By whom built \_\_\_\_\_ Owners *Hyde*  
 Port belonging to *London* Destined Voyage *Bombay & India*  
 If Surveyed Afloat or in Dry Dock *Afloat*

Original Survey, No. *77* Dated *April 1834* Classed *F.1*  
 Port *London*

## Repairs.

*At the present time caused from the copper on*  
*and the Decks - The rigging overhauled and <sup>upset</sup>*

General Observations  
 and Opinion, as  
 required by the  
 Instructions.

*Not Decked to  
 examine copper*

*The appearance of this ship is favorable  
 throughout and in my opinion she is still  
 in an efficient state of repair for the conveyance  
 of dry and perishable cargoes and ought to  
 remain classed F.1*

*George Beyley*

The Amount of Fee..... £ : : is received by me.

Committee Minute *3 November* 1835

Character assigned

*Continue the class*  
*M.H.*