

REPORT of SURVEY for REPAIRS.

2127

No. 2127 Survey held at London Date January 2nd 1836
 on the Ship Egyptian Master Butcher
 Tonnage 359 Built at Shields When built 1825
 By whom built _____ Owners Tenwick & Co
 Port belonging to Newcastle Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock during repairs

Original Survey, No. 403 Dated July 1834 Classed K.1
 Port London

Repairs. At the present time in consequence of having been on shore in the Gulf of St Lawrence - All the Hanging Bolts to the Hold Beams, several Bolts in the Wood Lodging Knees, and the Upper Deck Fastenings shifted, several Trunnels shifted & Planks of the Ceiling shifted at the 1st Head, New False Keel - New Planks were fore and aft Caulked from the Keel to the Waterway Seam - The Topsides scraped bright, and carefully examined - Upper Course Wood sheathed and Felted, & recooped - Rudder examined, and finally overhauled.

General Observations and Opinion, as required by the Instructions.

The Timber seen where the Planks of the Ceiling were shifted - in very good condition of large scantling Dry and Firm abaft - Her whole appearance is very favorable and in my opinion she is entitled to remain classed K.1

George Bayley

The Amount of Fee £ 2 : 2 : 0 is received by me.

Committee Minute 19 January 1836

Character assigned Record Repairs & continue Class K.1

Tenwick & Co
Surveyors at Shields