

2274

REPORT of SURVEY for REPAIRS.

No. 2274 Survey held at London Date March 6th 1836
 on the Bark Crator Master Ferry
 Tonnage 321 Built at Sunderland When built Dec^r 1835
 By whom built Austin Owners Allen Ho^r? Mr. Chapman
 Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Wess^t Jetty Ho^r Dock Newbrance
See Sunderland Survey No 365 & London Survey No 2194 Classed 10A

Original Survey, No. _____ Dated Feb^r 1836 Classed 10A1
 Port London & Sunderland

Repairs. At the present time a Pair of Staple Standards have been put in as recommended - 2 Shakes of the upper Course felled - and the Bottom sheathed with Copper

General Observations and Opinion, as required by the Instructions

The additional fastenings having been put in as recommended - I am of opinion that her class should be raised to 11A1 and therefore recommend that her clasping should be reconsidered

George Bayley

No Fee

The Amount of Fee..... is received by me.

London Surveys
 see 2594
 Index - 365

Committee Minute 11 March 1836

Character assigned Raise the Class to 11A1

