

REPORT of SURVEY for REPAIRS.

No. 2355 Survey held at London Date 28th March 1836
on the Brig Salladen Master R. Gould
Tonnage 264 Built at Lunderland When built 1825
By whom built _____ Owners Hughes
Port belonging to Swanville Destined Voyage Quebec
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2322 Dated March 8th 1836 Present Month Closed E. 2
Port London

Repairs. At the present time New Beam under Head of Bowsprit
Partially caulked and Supplied with New Hardware

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
Spirketting _____
Plank Shears _____
Topsides In fair
Upper Deck with its Appendages Condition
Lower Deck Fastenings _____

Wales _____
Counter _____
Plank and Treennails _____
(Outside to the Water's Edge.)
Rudder In fair Condition
Windlass _____
Capstan _____

General Observations and Opinion, This vessel has now undergone the repairs of
as required by the Instructions,
which I recommended on a former occasion and in my opinion
may now be closed. W. May

The Amount of Fee.....£ _____ is received by me.

Committee Minute 29 March 1836

Character assigned Raise to B. 1. W. May