

ANNUAL SURVEYS.

1388
784

No. 2388 Survey held at London Date 9 April 18 36
 on the Brig Brothers Master Davis
 Tonnage 142 Built at New Brunswick When built 1829
 By whom built — Owners Spark
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 658 Port of London Classed A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	

General Observations and Opinion, And new Knight Head about 2 months since
 as required by the Instructions, is now in fair condition following up from
and may in my opinion be continued in her present Class A.

Committee Minute 19 April 1836

Character assigned Continue Class B.1 SB

Stannaway

No. 736 Survey held at London Date 11 April 18 36
 on the Bark Mary Tainy Master Marer
 Tonnage 316 Built at Sunderland When built 1834
 By whom built T. Tainy Owners T. Tainy
 Port belonging to Sunderland Destined Voyage Home
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 27 Port of Sunderland Classed C.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	

General Observations and Opinion, No appearance of decay in any part fastenings
 as required by the Instructions, are firm is now supplied with 3 more brass anchors
and in my opinion may be continued in her present Class

Committee Minute 19 April 1836

Character assigned Continue Class C.1 SB

Stannaway
 © 2019
 Lloyd's Register
 Foundation

6510-66510