

REPORT of SURVEY for REPAIRS.

No. 2622 Survey held at London Date March 9 1836
 on the Brick Macassar Master Murray
 Tonnage 126 Built at P.R. Island When built 1828
 By whom built _____ Owners Speck & Co
 Port belonging to London Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock Master's Dry Dock

Original Survey, No. 1266 Dated March 1835 Classed A.1
 Port London

Repairs. *At the present time Cuckew Brunt Hooks Two new Beams (Lower Deck) and Stringer under Lower Deck Beams generally examined.*

The general appearance is very favorable
 General Observations *throughout, the fastenings in good condition*
 and Opinion, as *Rudder good - Plank, Decks, Waterways, Mast & Masts,*
 required by the *Landson in good order - Sails & Stores the same*
 Instructions. *I am of opinion that she should remain classed*
A.1 *George Bayley*

The Amount of Fee £ 2 : 2 : 0 is received by me. at the Office

Committee Minute 12 July 1836

Character assigned Repairs & continued class A.1
M.H.S.