

# ANNUAL SURVEYS.

2874  
JH

No. 2074 Survey held at London Date Oct 8<sup>th</sup> 1836  
 on the Brig Harriet Master Midwinter  
 Tonnage 1175 Built at Yarmouth When built 1833  
 By whom built \_\_\_\_\_ Owners Gibbs  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Afloat in Green's Dry Dock

Original Survey, No. 1126 Port of London 1834 Classed 8A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	

General Observations and Opinion, At the present time Copper repaired and in good order  
 as required by the Instructions, This keel is throughout in good condition  
George Bayley

Committee Minute 18 October 1836

Character assigned Continued Class 8A JH

No. \_\_\_\_\_ Survey held at London Date Oct 8<sup>th</sup> 1836  
 on the Brig William Master Roberts  
 Tonnage 338 Built at Sunderland When built 1827  
 By whom built \_\_\_\_\_ Owners J Pirie  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Afloat in Green's Dry Dock

Original Survey, No. 550 Port of London 1834 Classed 10A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	

General Observations and Opinion, At the present time Copper repaired, in good condition  
 as required by the Instructions, The whole appearance is favorable  
George Bayley  
has not this keel been  
coppered since 1832? JH  
say in 1835.

Committee Minute 18 October 1836

Character assigned Continued Class 10A JH



© 2019

Lloyd's Register  
Foundation

LON600-6082