

Change of Property 3077

REPORT of SURVEY for REPAIRS.

No. ⁶⁸² 3077 Survey held at London Date January 21 1837
on the Brig Spring Master W. Batt
Tonnage 90 Built at Whitby When built 1807
By whom built _____ Owners Songridge J. L.
Port belonging to London Destined Voyage Glaucoster
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1409 Dated 1835 Classed "E, 1"
Port of London

Repairs. No repairs at the present time, or does she appear to
have any for some time

The Surveyor to state the present Condition of	
Upper Deck Fastenings	<u>Defective</u>
Spirketting	
Plank Shears	<u>Indifferent</u>
Topsides	<u>Fair condition</u>
Upper Deck with its Appendages	<u>Indifferent</u>
Lower Deck Fastenings	<u>Defective</u>
Wales	<u>Fair Condition</u>
Counter	<u>Very indifferent</u>
Plank and Treenails (Outside to the Water's Edge.)	
Rudder	<u>Good</u>
Winlass	<u>"</u>
Capstan	<u>None</u>

General Observations and Opinion, The decks and waterways are in a very indifferent
as required by the Instructions, state, the deck fastenings loose, several of the
beams decayed at the ends, ceiling decayed in
places, the timbers when seen much impaired
from age and a general appearance of weakness,
Sam. P. in opinion she should be classed E 1
The Amount of Fee.....£ 10 : 6 is received by me. at the Office
Wm. Whittaker

Committee Minute 24 Jan'y 1837

Character assigned Reduced to E 1 noting to Owners