

REPORT of SURVEY for REPAIRS.

No. _____ Port of London Date August 28 1835
 Survey of the Ship, Pelung Grove Master Salcove
 Tonnage 383 By whom built P. Mustard Where built London
 When built 1793 Owners Capt. H. C. Port belonging to London
 Destined Voyage Lamara
 Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. annexed Dated 1834

Port London

Repairs. At the present time has had new Stern Port and
 1st Transom shifted. Bottom caulked from
 Keel to trale. Ship hung and Keel seam caulked.
 Felted. Wood sheathed and Coppered.

General Observations
 and Opinion, as
 required by the
 Instructions.

This ship notwithstanding her age is now in good condition
 in all parts to which I could obtain access. The Stern
 Frame is in good condition. The general appearance
 in the Hold very firm. Males. Topsides, Bottoms
 Deck fastenings. Decks. & Breast Hooks are in
 good condition. The Watertway seam has opened
 a little & will be caulked before sailing.
 The Standing Rigging is stated to be 2 years old. is in good condition.
 Masts and Yards are in same state. Has 3 Bower Anchors
 10 lb and 4 Kedge Anchors. 255 fathoms Chain Cable &
 2 full suits of sails all in good order. She is in my
 opinion fit for the conveyance of dry and Requisite
 Cargoes & should be classed F. 1 George Bayley

The Amount of Fee..... £ — : — is received by me. See annexed Survey

Committee Minute _____ 183 _____

Character assigned _____



© 2019

Lloyd's Register
 Foundation

LON600-0323