

Exchanged Owners

Sur 1837

REPORT of SURVEY for REPAIRS.

No. 3383 Survey held at Lندن Date May 25 18 36
on the Brig, Indian Chief Master J. Hart
Tonnage 210 Built at St Andrew When built 1830
By whom built _____ Owners Barrington
Port belonging to Lندن Destined Voyage Archangel
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 3383 Dated Lندن

Port _____

Repairs.

At the present time called
is in very good condition, no appearance of
rotting at the beam ends, the decks, walls, stowage
casing, breasthooks & fastenings in good order and
I am of opinion is fit for the safe conveyance of
dry & heavy cargo.

Washed in 1833 was perfect

General Observations
and Opinion, as
required by the
Instructions.

Should be classed No. 1

Whiddister

[Signature]

The Amount of Fee £ is received by me.

Committee Minute _____ 183 _____

Character assigned See Annexed Survey