

ANNUAL SURVEYS.

357

No. 1085 Survey held at London Date 14 Nov 1837
 on the Parrots Vale Master Canny
 Tonnage 345 Built at Greenwich When built 1837
 By whom built S. Wilson Owners Edwards
 Port belonging to London Destined Voyage Madras & Co
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 173 Port of London & Greenwich Classed V.A.

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Abd. Had Pine</u>
Spirkettling	Topsides	Sails <u>See sails</u>
Plank Shears	Wales	Cables <u>240 fms Charn & Jeffries</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of <u>3 D 1 & 1 R</u>
Hatchway Coverings	Rudder	Standing & Running Rigging <u>See good quality</u>
	Windlass	Copper <u>See present time</u>

General Observations and Opinion. This Ship is now complete in her
 as required by the Instructions, Equipment and may have perhaps a
prejudice to her Character Porter
 Committee Minute 24 Nov 1837

Character assigned 12 A 1

No. 130 Survey held at London Date Nov 18 1837
 on the By Margaret Master Nickson
 Tonnage 251 Built at Greenwich When built 1824
 By whom built See Owners See
 Port belonging to Montreal Destined Voyage Amsterdam & Mauritius
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. Port of York Classed *A/1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion. New Spikes now put in at the bow which
 as required by the Instructions, is in poor condition in every respect
of the main hatchway is broken down
stated that they were intended to be made
 Committee Minute 24 Nov 1837
 Character assigned 12 A 1

Ad. 100-
23 Aug 1830

Charles the Clerk

HT

of



© 2019

Lloyd's Register
Foundation