

REPORT of SURVEY for REPAIRS.

No. 3303 Survey held at London Date Mar 18 77
 on the Suma Master Lee
 Tonnage 323 Built at Liverpool When built 1811
 By whom built _____ Owners James
 Port belonging to Liverpool Destined Voyage Transport
 If Surveyed Afloat or in Dry Dock By Dock

Original Survey, No. _____ Dated _____
 Port _____

Repairs. At the present time Shippers, including the coles and uncoopers port muntopsides and Ship Caulked aloft, and other general repairs,

The Surveyor to state the present Condition of

Upper Deck Fastenings	_____	Wales	_____
Spirkettling	_____	Counter	_____
Plank Shears	<u>In good</u>	Plank and Treennails (Outside to the Water's Edge.)	_____
Topsides	<u>Condition</u>	Rudder	<u>In good</u>
Upper Deck with its Appendages	_____	Windlass	<u>Condition</u>
Lower Deck Fastenings	_____	Capstan	_____

General Observations and Opinion,
 as required by the Instructions,

This Ship is Shld in very fair condition fastenings are firm is fit for the conveyance of dry and perishable and may be continued as classed.

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 183

Character assigned _____