

# REPORT of SURVEY for REPAIRS.

No. 3819 Survey held at London Date Dec 19 1837  
 on the Schoon Napoleon Master Childs  
 Tonnage 87 Built at Baltimore When built  
 By whom built Owners West African Co  
 Port belonging to London Destined Voyage Hernando Ro  
 If Surveyed Afloat or in Dry Dock Mr H. Stachwood Dry Dock

Original Survey, No. 2600 Dated London 1831 Classed A. 1  
 Port Dartmouth No 103

## Repairs

at the present time several planks of the Deck and one plank of the bale shifted - Timbers & Beams good - New Counter - Caulked from the Copper saw all - Windows fitted - Hooding lister - generally overhauled.

Dec 22<sup>nd</sup> The copper has the appearance of not having been in more than 3 years of service.

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
<u>Lower Deck Beams &amp; Fastenings</u>	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Trewnails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,  
 as required by the Instructions.

In my opinion this vessel is in an efficient state of repair for the safe conveyance of dry & perishable cargoes to & from all parts of the British should be classed A. 1

The Amount of Fee £ 10 : 6 is received by me

Committee Minute 22 Dec 18 37

Character assigned A. 1