

REPORT of SURVEY for REPAIRS.

3865
Change of Property

No. 3865 Survey held at London Date Jan'y 12th 1838
 on the Bg. Agnes Master Swanson
 Tonnage 203 Built at Dartmouth When built 1825
 By whom built _____ Owners Bullock & Co
 Port belonging to London Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 706 Dated 1835 Classed "B. 1"
 Port of Liverpool

Repairs. All the present time the approaches caulked

The Surveyor to state the present Condition of

Upper Deck Fastenings _____ Spirketting _____ Plank Shears _____ Topsides _____ <u>good</u> Upper Deck with its Appendages _____ Lower Deck Fastenings _____	Wales _____ Counter _____ Plank and Treennails _____ <small>(Outside to the Water's Edge)</small> Rudder _____ <u>good</u> Windlass _____ Capstan _____
---	---

General Observations and Opinion, As in very good condition & firm at her
 as required by the Instructions, fastenings & Part of Spar in may retain
her present Place A. 1

The Amount of Fee £ 1 : 1 : - is received by me Wm. Miller
 Committee Minute 16 Decr 1838
 Character assigned A. 1



© 2019
 Lloyd's Register
 Foundation

LON 603-0037