

ANNUAL SURVEYS.

4057

No. 1054 Survey held at London Date April 5th 1830
 on the Bay Cardiff Packet Master Jones
 Tonnage 57 Built at Cardiff When built 1824
 By whom built _____ Owners Cardiff Shipping Company
 Port belonging to Cardiff Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 264 22034 Port of London

Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>Fair</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting _____	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways <u>Defective</u>	Plank and Treenails _____	Anchors No. of _____
Hatchway Comings <u>Fair</u>	(Outside to the Water's Edge)	Standing & Running Rigging _____
	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion, This day left notice in writing recommending new planks
 as required by the Instructions, shear waterways in every other respect is in very fair
condition, and when the above repairs are done am of
opinion she may be continued A. 1

Committee Minute 14 April 1830

Character assigned A. 1

No. 168 Survey held at London Date April 5th 1830
 on the Bay Edward Brothers Master Edwards
 Tonnage 101 Built at Chelston When built 1824
 By whom built _____ Owners Captain G. P.
 Port belonging to Newport Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 29 Port of Waterford

1035

Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>Fair</u>	Breasthooks <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting _____	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways <u>Defective</u>	Plank & Treenails _____	Anchors No. of _____
Hatchway Comings <u>Fair</u>	(Outside to the Water's Edge)	Standing & Running Rigging _____
	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion, The Waterways & Shear strake and deck Defective and
 as required by the Instructions, the ceiling much decayed this day left notice recommending
the above to be made good in her present state I am
of opinion she is not fit for the safe carriage of
inferior & combustible cargoes and should be classed B. 1

Committee Minute 14 April 1830

Character assigned Reduced to B. 1