

ANNUAL SURVEYS.

4081

No. 4081 Survey held at London Date April 14th 18 30
 on the Ship Jeremiah Master J. Binner
 Tonnage 85 Built at Guercidine When built 1813
 By whom built _____ Owners Captain
 Port belonging to Guercidine Destined Voyage Barbary
 If Surveyed Afloat or in Dry Dock on the Mags

[Handwritten signature]

Original Survey, No. 162-273 Port of South Classed A. 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchor No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

[Handwritten: good]

[Handwritten: sound]

[Handwritten: well found]

General Observations and Opinion. *At the present time bottom caulked & examined as required by the Instructions, and was in an efficient state for the safe conveyance of dry & perishable cargoes & may continue to be so.*

Committee Minute 20 April 1830
 Character assigned A. 1
[Handwritten signatures]

[Handwritten signature: W. Middleton]

No. 602 Survey held at London Date April 16th 18 30
 on the Ship Malta Master H. Boffe
 Tonnage 140 Built at Malta When built 1826
 By whom built _____ Owners Boothchild
 Port belonging to Malta Destined Voyage to the West Indies
 If Surveyed Afloat or in Dry Dock Afloat

[Handwritten signature]

Original Survey, No. 16522878 Port of London Classed A. 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchor No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

[Handwritten: good]

[Handwritten: sound]

[Handwritten: well found]

General Observations and Opinion. *At the present time Copper plated & partially caulked as required by the Instructions, & was in very good condition & may retain her present class A. 1*

Committee Minute 20 April 1830
 Character assigned A. 1
[Handwritten signatures]

[Handwritten signature: W. Middleton]
 Lloyd's Register Foundation