

ANNUAL SURVEYS.

4133

No. 4133 Survey held at London Date May 4 1838
 on the M^r Embridge late Laman Master Hill
 Tonnage 180 Built at London When built
 By whom built James H. Co. Owners James H. Co.
 Port belonging to London Destined Voyage South Sea & India
 If Surveyed Afloat or in Dry Dock On the information of J. H. Co. the Manager.

Original Survey, No. 258 Port of London

Classed A

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Copstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>all new</u>
Spicketing	Top-sides	Sails <u>2nd best new</u>
Plank Sheers	Wales	Cables <u>2nd chain of 3rd Iron 1st 3rd chain</u>
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchors No. of <u>3. 1. 2</u>
Hatchway Comings	Rudder	Standing & Running Rigging <u>all new</u>
	Windlass	Copper <u>L</u>

General Observations and Opinion.

As required by the Instructions

*This vessel has been raised & has some repairs
 made at once for particular of which see
 her Report. The work is well done & she is in
 my opinion efficient for her class.*

Committee Minute

Character assigned

A-1 Arthur George Dayley

No. 129 Survey held at London Date May 8th 1838
 on the Ship Carnatic Master Laird
 Tonnage 575 Built at Glasgow When built 1837
 By whom built Porter Owners 1st Port
 Port belonging to Glasgow Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Dowdson Dock

Original Survey, No. 357 Port of London

Classed 12A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Copstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>good</u>
Spicketing	Top-sides	Sails <u>white</u>
Plank Sheers	Wales	Cables <u>2nd chain new 3rd chain</u>
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchors No. of <u>3. 1. 1</u>
Hatchway Comings	Rudder	Standing & Running Rigging <u>good</u>
	Windlass	Copper <u>good - smooth</u>

General Observations and Opinion.

As required by the Instructions

*This is a well built ship and is in my opinion
 fully entitled to her present class 12A1*

Committee Minute

Character assigned

12A1 George Dayley