

REPORT of SURVEY for REPAIRS.

4268

Handwritten signature

No. 4268 Survey held at London Date June 16th 1830
 on the S^r Monkey Master Baynes
 Tonnage 114 Built at Hastings When built 1831
 By whom built _____ Owners J & J Adam
 Port belonging to London Destined Voyage Sister
 If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. 317, 338, 38 Dated 3/9/03 Classed 12 A 1
 Port of London

Repairs At the present time caulked & Coppered over paper

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Well</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Sound</u>
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Is in a very efficient state both in the Hull &
 as required by the Instructions, Stores and may retain her present Class

Handwritten signature

The Amount of Fee.....£ — : 10 : 6 is received by me, *Handwritten initials*

Committee Minute 3 July 1830

Character assigned 12 A 1

Handwritten signature

