

# ANNUAL SURVEYS.

4349

No. 4349 Survey held at LONDON Date July 17 1838  
 on the Bark Ralph Bernal Master  
 Tonnage 314 Built at Sunderland When built 1835  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to LONDON Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Liverpool Dock

Original Survey, No. 336 Port of Sunderland 1835 Classed 10A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time examined the copper and repaired it where necessary - Is in good condition in other respects and in my opinion should remain in her present class 10A1  
 as required by the Instructions.

Committee Minute 2 Aug 1838  
 Character assigned 10A1  
C. H. George Dayley

No. \_\_\_\_\_ Survey held at LONDON Date July 30<sup>th</sup> 1838  
 on the Bark Lindholm Master Collinson  
 Tonnage 329 Built at Montreal When built 1838  
 By whom built \_\_\_\_\_ Owners Collinson  
 Port belonging to LONDON Destined Voyage Montreal  
 If Surveyed Afloat or in Dry Dock Gun Dock

Original Survey, No. None Port of Will not have her Classed Classed \_\_\_\_\_

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, This ship has no hanging keels - She is a well built ship of her class - Carried keel to water  
 as required by the Instructions. George Dayley

Committee Minute \_\_\_\_\_ 183  
 Character assigned \_\_\_\_\_



© 2019

Lloyd's Register  
Foundation