

# REPORT of SURVEY for REPAIRS.

No. 4495 Survey held at London Date August 10<sup>th</sup> 1838  
 on the Boat Robert Master Herrick  
 Tonnage 310 Built at Greenock When built 1810  
 By whom built \_\_\_\_\_ Owners Nedues  
 Port belonging to London Destined Voyage Montserrat  
 If Surveyed Afloat or in Dry Dock Hacknott's Dry Dock

Original Survey, No. 61482766 Dated 1834 & 1836 Restored 1834 - 6 Years  
 Classed A 1  
 Port London

**Repairs** At the present time new half Deck with a break  
 properly secured and overhauled aloft  
 also the Masts doubled with two inch African Oak over  
 Patent Deck, & new Decks fore & aft and caulked from the  
 Copper upboards

*A. Middleton*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *In my opinion this ship is entitled to remain*  
 as required by the Instructions, *as at present classed A 1*

*George Bayley*

The Amount of Fee.....£ 2 : 2 : — is received by me, *HA*

Committee Minute 21<sup>st</sup> Sept<sup>r</sup> 1838

Character assigned A 1 6 Years