

# REPORT of SURVEY for REPAIRS.

4523  
JH

No. 4523 Survey held at London Date October 1<sup>st</sup> 1830  
 on the Schooner Eliza Ann Master T. J. Martyn  
 Tonnage 137 Built at New Brunswick When built 1816  
 By whom built \_\_\_\_\_ Owners John Rogers  
 Port belonging to London Destined Voyage Cape Coast Castle  
 If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. 54 Dated 1815 Classed S. S. 3 Years A. 1  
 Port London, Dartmouth, Liverpool No 1240 & London 3232 & 3955

**Repairs** At the present time bottom stumped, the Iron fastenings punched up, the butts in the upper course of the bottom & and lower Breasthook rebolted with Copper, caulked and recoppered over Felt

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, General appearance very good no symptoms of weakness  
 as required by the Instructions, or decay and I am of opinion may retain her  
present state

*W. Middleton*

The Amount of Fee.....£ — : 10 : 6 is received by me, JH

Committee Minute 5 Oct 1830

Character assigned A. 1 decayed repairs

