

ANNUAL SURVEYS.

4553

No. 4553 Survey held at London Date October 10 1838
 on the Bark Mary Loring Master Loring
 Tonnage 316 Built at Sunderland When built 1834
 By whom built Loring Owners Loring
 Port belonging to Sunderland Destined Voyage Honduras
 If Surveyed Afloat or in Dry Dock Supra Hatched Dry Dock

Original Survey, No. 2328 Port of London April 1836 Classed 6A1

Surveyor is required to state the present Condition of the

Deck Beams & Fastenings	Breasthooks <u>None one rebolted</u>	Capstan
Deck Beams & Fastenings	Transoms <u>Good</u>	Pumps <u>Good</u>
Spirkettling	Timbers of the Frame <u>4</u>	Masts, Yards, &c. <u>See</u>
Plank Shears	Topsides <u>4</u>	Sails <u>See</u>
Waterways	Wales <u>4</u>	Cables <u>See</u>
Hatchway Comings	Plank and Treenails <u>4</u>	Anchors No. of <u>3 - 1 - 1</u>
	(Outside to the Water's Edge)	Standing & Running Rigging <u>Good</u>
	Rudder <u>4</u>	<u>Repaired 1838</u>
	Windlass <u>4</u>	

General Observations and Opinion In my opinion this vessel is entitled
 as required by the Instructions to remain as at present classed 6A1

Committee Minute 16th Dec 1838

Character assigned 6A1

George Bayley



© 2019

Lloyd's Register
Foundation

CON603-C355