

# REPORT of SURVEY for REPAIRS.

4701

No. 4701 Survey held at LONDON Date Nov 28 1838  
 on the Boat Albion Master Barrett, Henry  
 Tonnage 178 Built at Manchester When built 1828  
 By whom built \_\_\_\_\_ Owners Burde  
 Port belonging to LONDON Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Mountain Dock

Original Survey, No. 1857 Dated 1835 Classed 10 A 1  
 Port LONDON

**Repairs** At the present time (having been ashore) studding  
 caulked from keel to wale & recoppered on paper  
 to 11 feet

The Surveyor is also required to state the present Condition of the

|                               |  |                            |
|-------------------------------|--|----------------------------|
| Decks                         | Transoms   | Windlass                   |
| Upper Deck Beams & Fastenings | Timbers of the Frame                                 | Capstan                    |
| Lower Deck Beams & Fastenings | Topsides   | Pumps                      |
| Spirkettling                  | Wales  | Masts, Yards, &c.          |
| Plank Shears                  | Counter  | Sails                      |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge) | Cables                     |
| Hatchway Comings              | Rudder   | Anchors No. of             |
| Breasthooks                   | Copper <u>1838</u>                                   | Standing & Running Rigging |

General Observations and Opinion,  
 as required by the Instructions,

This repairs copper was quite before stripping  
 in whole appearance favorable - In my opinion  
 this entitled to remain as classed 10A1

*George Bayley*

The Amount of Fee.....£ : 10 : 1 is received by me,

Committee Minute 4 Dec 1838

Master assigned 10 A 1 remain left

