

ANNUAL SURVEYS.

4756

No. 4756 Survey held at London Date Dec^r 18 1838
 on the Schooner Mary Master Sterry
 Tonnage 160 Built at Gravich When built 1835
 By whom built Wm Bayley Owners Havers & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Mountain Dock ways

Original Survey, No. 71 Port of Gravich 1835 Classed 1A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>up 1838</u>

General Observations and Opinion, At the present time no work is done. Lower clanks
 as required by the Instructions, shortened & the copper largely repaired - this
is my opinion entitled to remain as classed 1A1

Committee Minute 21 Dec 1838 George Bayley
 Character assigned 1A1

No. 4757 Survey held at London Date Dec^r 18 1838
 on the Brig X L Master Clough
 Tonnage 213 Built at Leby When built 1822
 By whom built London Owners Standing
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Church ways

Original Survey, No. 656 & 2712 Port of London Dec^r 1838 Classed *F.
& Hull 637 & London No 4703

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, The fastenings and repairs recommended & on which
 as required by the Instructions, the was conditionally classed *F. are now completed in
a satisfactory manner - 1 New Holdbeam & 1 new
4 pc & 1 Hkms. Cutch abaft 2 Planks of the Ceiling each
side, 1 pc turn of bridge shifted -

Committee Minute 21 Dec 1838 George Bayley
 Character assigned 1A1

9600-7007