

# REPORT of SURVEY for REPAIRS.

4828

No. 4828 Survey held at London Date Dec<sup>r</sup> 28 1838  
 on the Brig ~~Ulysses~~ Master W.C. Riley  
 Tonnage 181 Built at Yarmouth When built 1829  
 By whom built \_\_\_\_\_ Owners Clodwick  
 Port belonging to London Destined Voyage Cadiz  
 If Surveyed Afloat or in Dry Dock Gun Dock

Original Survey, No. 68 Dated 1834 Classed 12A1  
 Port Clyde

## Repairs

At the present time stopped, caulked keel  
 up and recoppered to 11 feet

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1838</u>	Standing & Running Rigging

} Good

} Good & Efficient

General Observations and Opinion,  
 as required by the Instructions,

In my opinion this vessel should not have  
 been classed originally more than 12A1. She  
 is now in an efficient state of repair.

The Amount of Fee.....£ 1 : 1 : is received by me,

Committee Minute 18 Jan 1839

Character assigned 12A1 assessed app



© 2019

Lloyd's Register  
 Foundation

LON 604-0174