

REPORT of SURVEY for REPAIRS.

No. 4878 Survey held at London Date 9th 33rd 1839
 on the M William & Alfred Master Culverwell
 Tonnage 388 Built at Hull When built 1831
 By whom built — Owners J Head
 Port belonging to London Destined Voyage West India
 If Surveyed Afloat or in Dry Dock Dry Dock & Afloat

Original Survey, No. 256 & 4253 Dated _____ A. 1

Port London

Repairs. At the present time at my suggestion new upper piece of skin apron and head, port new valves, 4th new block strokes, bottom stripped caulked from the keel up, fitted shothen and coppered, and generally overhauled,

The Surveyor to state the present Condition of

Upper Deck Fastenings _____

Spirketting _____

Plank Shears 2 1/2 yds

Topsides _____

Upper Deck with its Appendages

Lower Deck Fastenings _____

Wales

Counter _____

Plank and Treenails
(Outside to the Water's Edge)

Rudder *Thru*

Windlass

Capstan

*General Observations and Opinion,
as required by the Instructions.*

General Observations and Opinion,
as required by the Instructions,

The lumber exposed in Shifting the plank were found good The condition of this ship is now so much improved that in my opinion she is now fit for the conveyance of any species of cargo

The Amount of Fee..... £ 2 : 2 : — is received by me. *W. H. & from all parts of*

Committee Minute 5 Feb 183 9

Character assigned

C. F. SEYFANG, PRINTER, FARRINGTON STREET, LONDON