

REPORT of SURVEY for REPAIRS.

No. 137 Survey held at London Date 15 Feb 1839
on the M Caroline Master Hopper - F Anderson
Tonnage 425 Built at Quebec When built 1828
By whom built - Owners J Allan
Port belonging to London Destined Voyage Quebec
If Surveyed Afloat or in Dry Dock Gordon's Dock

Original Survey, No. 1205, 2406 & 327 Dated - Classed 7 A 1
Port London

Repairs. At the present time, 3 new Hold Beams, 4 knees to the same 2 new Breast Hooks, new culing at the bows Bottom Couked, filled & sheathed with board 4 large Iron Riders and Crutch put in in after body

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Sufficient</u>
Plank Shears <u>Sufficient</u>	Counter <u>Sufficient</u>	Sails <u>none</u>
Waterways <u>Antidivion</u>	Plank and Treenails (Outside to the Water's Edge) <u>Condition</u>	Cables <u>gone</u>
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, This ship has been opened in conformity with the Society Rules and several timbers on each side in the after body becoming soft, 4 very large Iron Riders and a crutch put in at my suggestion to compensate where seen in other parts she appears very sound is now in good
as required by the Instructions, and efficient condition

The Amount of Fee.....£ 2 : 2 : - is received by me, (except as above) and for the conveyance of day and perishable cargo and may be continued as charged
Committee Minute 5 March 1839
Character assigned A 1 S S 2 Mar 1839

Letter to Oliver S March 1835



© 2019
Lloyd's Register
Foundation