

REPORT of SURVEY for REPAIRS.

4984

No. 510 Survey held at London Date March 9th 1834
 on the S^r Abion Master T^r Taylor
 Tonnage 04 Built at Boston When built 1826
 By whom built _____ Owners J Hudson & Co
 Port belonging to Boston Destined Voyage Hambro
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 67 Dated 1835 Classed 10 A 1 now B
 Port of Penzance

Repairs In 1830 new keel, stem post, part new Bottom,
partly retreenails, caulked and a general overhauled

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	<u>Copper</u>	Standing & Running Rigging

General Observations and Opinion, Is in very good condition throughout no appearance
 as required by the Instructions, of weakness or decay & fit for the safe conveyance
of dry & perishable cargoes, and may be classed F.1

W. Middleton

The Amount of Fee.....£ — : 10 : 6 is received by me, W. Middleton into the Office

Committee Minute 12 March 1834

Character assigned F.1 renewed repairs