

5086

Annual?

REPORT of SURVEY for REPAIRS.

No. 51 Survey held at London Date March 25 1839
 on the Brig Union Master Rosen
 Tonnage 208 Built at Guscomb When built 1803
 By whom built _____ Owners Richmond
 Port belonging to London Destined Voyage Coal Trade
 If Surveyed Afloat or in Dry Dock Ratcliff Crossways

Original Survey, No. 97 Dated _____ Classed E1
 Port London Cardiff

Repairs Cancelled to Bilge but Vayage. 4 Hauling of the Deck ship to at present time -

The general appearance of this vessel is fair & good -

The Surveyor is also required to state the present Condition of the

| | | |
|-------------------------------|--|----------------------------|
| Decks | Transoms | Windlass |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Capstan |
| Lower Deck Beams & Fastenings | Topsides | Pumps |
| Spirketting | Wales | Masts, Yards, &c. |
| Plank Shears | Counter | Sails |
| Waterways | Plank and Treenails (Outside to the Water's Edge) | Cables |
| Hatchway Comings | Rudder | Anchors No. of |
| Breasthooks | Copper | Standing & Running Rigging |

Handwritten notes: "Fair" for Decks, "Good" for Wales, Counter, and Masts, Yards, &c.

General Observations and Opinion,
 as required by the Instructions,

In my opinion she is fully eligible to be present Class E1

Handwritten signature: George Bayley

The Amount of Fee.....£ 1 : 1 : is received by me, *Handwritten initials*

Committee Minute 26 Feb 1839

Character assigned E1 under repair