

REPORT of SURVEY for REPAIRS.

536

No. 716 Survey held at Liverpool Date 15 June 1839
 on the My Arab Master White
 Tonnage 184 Built at Liverpool When built 1825
 By whom built - Owners Gosshute
 Port belonging to Liverpool Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock A C My Book

Original Survey, No. 539, 13/4 Dated 1848 Classed A1
 Port Liverpool

Repairs At the present time in consequence of damage
 15 futtocks Starboard Stunson & Breast Hook, new
 belye stokes & some new caulking coaked all over
 new deck fastenings & shortly new treenails to copper

The Surveyor is also required to state the present Condition of the

| | | |
|-------------------------------|--|----------------------------|
| Decks | Transoms | Windlass |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Capstan |
| Lower Deck Beams & Fastenings | Topsides | Pumps |
| Spirkettling | Wales | Masts, Yards, &c. |
| Plank Shears | Counter | Sails |
| Waterways | Plank & Treenails (Outside to the Water's Edge) | Cables |
| Hatchway Comings | Rudder | Anchors No. of |
| Breasthooks | Copper | Standing & Running Rigging |

General Observations and Opinion,
 as required by the Instructions, *On opening her bows and down at the
 timbers were found very good she is now in the
 most efficient condition fit for the conveyance
 of dry & perishable cargo to & from all parts of the
 world & may be*

The Amount of Fee.....£ 1 : 1 : is received by me, *James H. H. H.*
 Committee's Minute 28 June 1839
 Character assigned A1



Big Arab

No. 111111

1155



© 2019

Lloyd's Register
Foundation