

# ANNUAL SURVEYS.

5444

No. 496 Survey held at London Date July 10 1839  
 on the Barque Joseph Storey Master Whitfield  
 Tonnage 266 Built at Sunderland When built 1830  
 By whom built \_\_\_\_\_ Owners Quatro & Co  
 Port belonging to London Destined Voyage Peterburgh  
 If Surveyed Afloat or in Dry Dock at Chittels ways

Original Survey, No. 476, 476 Port of London December 1838 Classed 10A1  
15408

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper raised one stanchion

General Observations and Opinion, at the present time new false Port, & Reason repaired rudder,  
 as required by the Instructions, the ship in good and efficient condition and in my  
opinion eligible to remain as classed 10A1

Committee Minute 19 July 1839

Character assigned 10A1

No. 350 Survey held at London Date July 12 1839  
 on the Ship Windsor Master Verbitt  
 Tonnage 676 Built at Blackwall When built 1835  
 By whom built Jam & Co Owners R Green  
 Port belonging to London Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Blackwall Dry Dock

Original Survey, No. 4698 Port of London June 1838 Classed 12A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>ref</u>

General Observations and Opinion, at the present time sailed from their straits up  
 as required by the Instructions, is in good and efficient condition & eligible to  
remain as at present classed 12A1

Committee Minute 19 July 1839

Character assigned 12A1



© 2019

Lloyd's Register  
Foundation

1- 1<sup>st</sup> Entry  
3 Repairs  
4 Annual  

---

8



© 2019

Lloyd's Register  
Foundation