

ANNUAL SURVEYS.

No. 5472 Survey held at London Date June 23rd 1839
 on the St Ann Master Hailstone
 Tonnage 90 Built at Yarmouth When built 1831
 By whom built _____ Owners J. Fletcher
 Port belonging to London Destined Voyage Goole
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 510 Port of London 1834 Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks <u>Sound</u>	Capstan <u>None</u>
Upper Deck Beams & Fastenings	Transoms <u>"</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings	Timbers of the Frame <u>Sound when seen</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Well found</u>
Plank Shears	Wales <u>"</u>	Cables <u>"</u>
Waterways	Plank and Treenails <u>"</u> (Outside to the Water's Edge)	Anchors No. of <u>"</u>
Hatchway Comings	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>"</u>	<u>WPA</u>

General Observations and Opinion, Caulked at the present time caulked & treenails
 as required by the Instructions, examined, in good condition & may continue
in her present shape

Committee Minute 28 June 1839

Character assigned 10 A 1

No. 227 Survey held at London Date June 26th 1834
 on the St Glory Master May
 Tonnage 132 Built at Colechester When built 1825
 By whom built _____ Owners Capper & Co
 Port belonging to London Destined Voyage Hambro
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2167 Port of London 1836 Classed A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks <u>Sound</u>	Capstan <u>None</u>
Upper Deck Beams & Fastenings	Transoms <u>"</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings	Timbers of the Frame <u>Sound when seen</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>"</u>
Plank Shears	Wales <u>"</u>	Cables <u>Well found</u>
Waterways	Plank & Treenails <u>"</u> (Outside to the Water's Edge)	Anchors No. of <u>"</u>
Hatchway Comings	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, At the present time caulked & a general overhaul
 as required by the Instructions, in an efficient state for the safe conveyance
of dry & perishable cargoes & may retain her
present shape

Committee Minute 28 June 1839

Character assigned A 1