

# ANNUAL SURVEYS.

5528

No. 32 Survey held at London Date August 12 1839  
 on the Ship Lady Flora Master Ed  
 Tonnage 756 Built at Calcutta When built 1814  
 By whom built \_\_\_\_\_ Owners Ed & Co  
 Port belonging to London Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock Imp. Peters Dock & Afloat

Original Survey, No. 14485 Port of London 1838 Classed \*A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

*Good* *Good* *Overhauling Main and Foremasts and*

General Observations and Opinion, *At the present time ~~exam~~ from the Copper on and overhauling*  
 as required by the Instructions, *aloft - It is in good and efficient condition to remain*  
*as classed \*A.1*

Committee Minute 13 Aug 1839

Character assigned A.1  
*Ch*

*George Bayley*

No. 25 Survey held at London Date August 12 1839  
 on the Ship Lady East Master Emery  
 Tonnage 648 Built at Calcutta When built 1816  
 By whom built \_\_\_\_\_ Owners Holdenup  
 Port belonging to Liverpool Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Blackwall Dry Dock

Original Survey, No. 1057, 1410 Port of Liverpool 1838 Classed A.1  
1647, 2202

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

*Good* *Good* *Good & efficient*

General Observations and Opinion, *Docked to examine copper found in a good sufficient*  
 as required by the Instructions, *state shigible to remain as classed A.1*

Committee Minute 13 Aug 1839

Character assigned A.1  
*Ch*

*George Bayley*



© 2019

Lloyd's Register  
Foundation

LON 605-0426



August 12<sup>th</sup>

At Annals

At Repairs

£



© 2019

Lloyd's Register  
Foundation