

# ANNUAL SURVEYS.

5623

No. 318 Survey held at London Date Sept 13<sup>th</sup> 1839  
 on the Bk Min Master Woodward  
 Tonnage 200 Built at London When built 1820  
 By whom built \_\_\_\_\_ Owners Darcy  
 Port belonging to London Destined Voyage Valparaiso  
 If Surveyed Afloat or in Dry Dock in the London Dock

Original Survey, No. 2507, 3874 Port of London 1830 Classed Continued 3 yrs per 1836

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, In a very efficient state both in the Hull & stores  
 as required by the Instructions, and may retain her present Class

Committee Minute 17 Sept 1839  
 Character assigned Cont. 3 A-1

No. 322 Survey held at London Date Sept 11<sup>th</sup> 1839  
 on the Sp 2 Min Master Forrest  
 Tonnage 273 Built at Chepstow When built 1824  
 By whom built \_\_\_\_\_ Owners Davidson & Barkly  
 Port belonging to London Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock in the West India Dock

Original Survey, No. 1264, 3182 Port of London Jan'y 1839 Classed A. 1  
3582, 4119, 4810,

The Surveyor is required to state the present Condition of the

Decks <u>Very fair Condition</u>	Breasthooks <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good &amp; Firm</u>	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame <u>sound &amp; unscor'd</u>	Masts, Yards, &c.
Spirkettling <u>Good</u>	Topsides	Sails <u>Well frayed</u>
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging <u>Good</u>
	Windlass	Copper

General Observations and Opinion, At the present a plank in the decks shifted next the  
 as required by the Instructions, Waterway, is in very good condition, and I am of opinion  
in an efficient state to retain her present Class

Committee Minute 17 Sept 1839  
 Character assigned A-1

6900-909N07