

## ANNUAL SURVEYS.

5655

No. 61 Survey held at London Date 20 Aug 18 39  
 on the Thames Master Barclay  
 Tonnage 457 Built at London When built 1829  
 By whom built London Owners Hibberts  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 882,2700 Port of London Classed 12 A1  
3462, 4287

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of <u>8 B 22 cut</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,  
 as required by the Instructions,

She appears every where in good sound Condition and may be recommended as classed

Committee Minute 24 Sept 1839

Character assigned 12 A1

No. 144 Survey held at London Date 9 Sep 18 39  
 on the Edgar Master Thompson  
 Tonnage 166 Built at Bristol When built 1834  
 By whom built London Owners J Morgan  
 Port belonging to London Destined Voyage —  
 If Surveyed Afloat or in Dry Dock Crop May

Original Survey, No. 73 Port of Bristol, London 2300, 5145 Classed 10 A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Sufficient</u>
Plank Shears <u>Condit</u>	Wales <u>Condit</u>	Cables <u>Good</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of <u>—</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,  
 as required by the Instructions,

Is in good Condition and may be recommended as classed

Committee Minute 24 Sept 1839

Character assigned 10 A1



© 2019

Lloyd's Register  
Foundation