

# ANNUAL SURVEYS.

5690

No. 313 Survey held at London Date Sept 26 18 39  
 on the Ship London Master Kent  
 Tonnage 441 Built at London When built 1813  
 By whom built \_\_\_\_\_ Owners H. J. J. J.  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock clap King Dry Dock

Original Survey, No. 1799, 2656 Port of London Nov. 1838 Classed A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder <u>New Main Piece 1839</u>	Standing & Running Rigging
	Windlass <u>Good</u>	Copper <u>rep<sup>d</sup> 1839</u>

General Observations and Opinion, In my opinion this ship is fully eligible to  
 as required by the Instructions, be present class A.1  
George Bayley

Committee Minute 4 Oct 1839

Character assigned A.1  
LB

No. 764 Survey held at London Date Sept 26 18 39  
 on the Bk Miranda Master Lowell  
 Tonnage 300 Built at Bristol When built 1828  
 By whom built \_\_\_\_\_ Owners Bateman  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Globe Dock

Original Survey, No. 390 Port of London, Ply. 97. Lon. 3634. 1837 Classed 10 A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks <u>some bolts shifted</u>	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, at the present time generally abackhauled and  
 as required by the Instructions, several breast hook bolts shifted - in my opinion  
this for the present eligible to the class A.1  
George Bayley

Committee Minute 4 Oct 1839

Character assigned A.1  
LB