

# ANNUAL SURVEYS.

5870

No. 653 Survey held at London Date Nov 25<sup>th</sup> 1839  
on the Cygnetto Master Manay  
Tonnage 151 Built at Fishburne When built 1826  
By whom built \_\_\_\_\_ Owners Samuel  
Port belonging to London Destined Voyage Africa  
If Surveyed Afloat or in Dry Dock in the Mays

Original Survey, No. 2396, 3925 Port of London  
4383

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time Caulked from the Copper upward  
as required by the Instructions, Coppered a sheet higher Channels taken down & a general  
overhaul in the Hull & Rigging, and is now in a very efficient  
state for the safe conveyance of Dry & perishable cargoes  
to all parts of the World and may be classed 12 A 1

Committee Minute

Character assigned

No. 53 Survey held at London Date Nov 25<sup>th</sup> 1839  
on the Cape Packet Master Samt  
Tonnage 303 Built at Sunderland When built 1830  
By whom built \_\_\_\_\_ Owners Samt  
Port belonging to London Destined Voyage Cape & Good Hope  
If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. 1039 Port of Sunderland

1830 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Caulked from the Copper to the Gunwale  
as required by the Instructions, Is in a very efficient state and may continue as classed

Committee Minute

Character assigned