

ANNUAL SURVEYS.

5932

No. 590 Survey held at London Date Decr 28 1839
 on the Back Matilda Luckie Master Mowbray
 Tonnage 275 Built at London When built 1834
 By whom built _____ Owners Luckie
 Port belonging to London Destined Voyage Dumfries
 If Surveyed Afloat or in Dry Dock Dowson's Dry Dock

Original Survey, No. 1014, 2421, Port of London 1837 Classed 10 A 1
3123, 3569

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>New Brunswick</u>
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>rep. good fair order</u>

General Observations and Opinion,
 as required by the Instructions,

*This vessel is in good and efficient condition
 in my opinion eligible to remain as
 classed 10 A 1*

Committee Minute 31 Dec 1839

Character assigned 10 A 1

George Bayley

No. 474 Survey held at London Date Decr 28 1839
 on the Schooner Clementina Master Wootton
 Tonnage 118 Built at Bowes When built 1836
 By whom built White Owners Williams
 Port belonging to London Destined Voyage St Michaels
 If Surveyed Afloat or in Dry Dock Afloat at Fresh Wharf

Original Survey, No. 32 Port of Bowes London 5530, 1836 Classed 11 A 1
Bowes 70.

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

*Since this vessel was last seen by me in December 1836
 he has had an additional Breast Hook & on don knee butts
 all the deck beams - an opening has been cut 4 strokes below
 the deck to show the frame, which is square and free from
 sap at that place - There is now no
 apparent cause for present her standing*

Committee Minute 31 Dec 1839

Character assigned 11 A 1

George Bayley