

REPORT of SURVEY for REPAIRS.

Change of Owners

6099

No. ²¹⁵ Survey held at London Date Febry 19th 1840
 on the Bk William Brodrick Master Edmonds
 Tonnage 2010 Built at Whitby When built 1836
 By whom built _____ Owners Edmonds
 Port belonging to London Destined Voyage Petersburgh
 If Surveyed Afloat or in Dry Dock in the Hoop

Original Survey, No. 42 Dated 1836 Classed 10 A 1
 Port of Whitby

Repairs Bottom examined & Bulks caulked

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>&</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables <u>Efficient</u>
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging _____

General Observations and Opinion, Ship in very good condition both in the Hull & Stores
 as required by the Instructions, and may continue her present Class

Alfred W. ...

The Amount of Fee.....£ 1 : 1 : is received by me, *[Signature]*

Committee's Minute 28th Febry 1840

Character assigned 10 A 1

