

# ANNUAL SURVEYS.

6100

No. 85 Survey held at London Date Feb'y 24<sup>th</sup> 1840  
 on the By Patriot Master J Webster  
 Tonnage 261 Built at Montrose When built 1833  
 By whom built \_\_\_\_\_ Owners Davidson  
 Port belonging to \_\_\_\_\_ Destined Voyage Constantinople  
 If Surveyed Afloat or in Dry Dock in the St Katharine's Dock

Original Survey, No. \_\_\_\_\_ Port of Dundee 1839 Classed 7A1  
London 2215, Montrose 158,

The Surveyor is required to state the present Condition of the

Decks	Breasthooks <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings	Transoms <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings	Timbers of the Frame <u>Sound &amp; secure</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>Good</u>	Topsides <u>Good</u>	Sails <u>Well &amp; good</u>
Plank Shears	Wales <u>"</u>	Cables <u>"</u>
Waterways	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>"</u>	Copper <u>Good</u>

General Observations and Opinion,  
 as required by the Instructions,

Whence Copper fastened

Is in a very efficient state and appears eligible  
 to retain her present Class

Committee Minute 28<sup>th</sup> Feb'y 1840

Character assigned 7A1

No. 152 Survey held at London Date Feb'y 25<sup>th</sup> 1840  
 on the By Apicarius Master J Scott  
 Tonnage 1035 Built at Yarmouth When built 1830  
 By whom built \_\_\_\_\_ Owners Forster & Co  
 Port belonging to London Destined Voyage Gambia  
 If Surveyed Afloat or in Dry Dock in Smith's Way

Original Survey, No. 235 Port of Yarmouth 1830 Classed 12A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>Good</u>	Topsides	Sails <u>Well &amp; good</u>
Plank Shears	Wales <u>Good</u>	Cables <u>Good</u>
Waterways	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,  
 as required by the Instructions,

Is in a very high state of efficiency and appears  
 eligible to retain her present Character

Committee Minute 28<sup>th</sup> Feb'y 1840

Character assigned 12A1



© 2019

Lloyd's Register  
 Foundation