

ANNUAL SURVEYS.

6140

No. 53 Survey held at London Date Feb 24-28 1840
 on the Ship James Harris Master Bright
 Tonnage 340 Built at Liverpool When built 1844
 By whom built _____ Owners Bright & Co.
 Port belonging to London Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock Pitcher Dock

Original Survey, No. 4044, 4046 Port of London Feb 1839 Classed E1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder <u>new 1840</u>	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, at the present time listed Goodies fitted
 as required by the Instructions, a falseport new Rudder - Is very strong
and is fully eligible to be present class E1

Committee Minute 10th March 1840

Character assigned E1

George Bayley

No. 90 Survey held at London Date March 4th 1840
 on the Ship Westford Master Litchie
 Tonnage 507 Built at Port of London When built 1834
 By whom built _____ Owners Harrison
 Port belonging to London Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock Douglas Dock

Original Survey, No. Bristol 80, 3302 Port of London 1837 Classed SA1 now B1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, at the present time caulked from the keel up
 as required by the Instructions, trim and sound - gave notice to open and put in
fastenings in accordance with Rule. which the
owner declines doing

Committee Minute 10th March 1840

Character assigned SA1

George Bayley

George Bayley
has not opened
I want add fastenings

March 9-

4 Annual

9. Report on

13



© 2019

Lloyd's Register
Foundation