

# ANNUAL SURVEYS.

6190

No. 3 Survey held at London Date Mar 23 18 40  
 on the Brig Athena Master Stearns  
 Tonnage 174 Built at London When built 1825  
 By whom built        Owners         
 Port belonging to London Destined Voyage Spain  
 If Surveyed Afloat or in Dry Dock Backward Dry Dock

Original Survey, No. 896, 2670, Port of London Sept 1838  
3526, 4519, 5422.

Classed F.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,  
 as required by the Instructions,

Copper repaired & overhauled, aloft appears  
eligible to remain as classed F.1

Committee Minute

27 March 1840

Character assigned

F.1, 1 Asterisk

George Bayley

No. 892 Survey held at London Date Mar 23 18 40  
 on the Brig British Tar Master Seddon  
 Tonnage 383 Built at London When built 1824  
 By whom built        Owners         
 Port belonging to London Destined Voyage         
 If Surveyed Afloat or in Dry Dock Rep'd Fletcher Dry Dock

Original Survey, No. 573, 2130, Port of London  
3079, 3024, 5427.

1837 Classed F.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,  
 as required by the Instructions,

Copper stripped off & bottom blacked - 4 Strakes of Sides  
amidships shifted on Starboard Side & on Starboard Side in  
wake of Chain Plates - New Churns & Bolts - One plank in  
hole on Starboard Bow & the plank next the Waterway on both  
sides. In my opinion she is eligible to remain as classed F.1

Committee Minute

27 March 1840

Character assigned

F.1

George Bayley



Mar 20

4 Papers

2 Annuals

1 Specimen

7



© 2019

Lloyd's Register  
Foundation